

Location key

Administration (ADM) D9	Franciscan E7	Physical Therapy C7
Alumni House B2	Garden of Remembrance D6	Public Safety (Police) B2
Bookstore D7	Gymnasium (GYM) B6-C7	Recycling C5
Burk Hall (BH) D6	Health Center C5	Science (SCI) B8-B9
Business (BUS) C8	Henshill Hall (HH) C8	Seven Hills Center D2
Cesar Chavez Student Center D7	HSS C9	Shipping & Receiving A3
Car Rental Lot 25 Winston Dr./ A1	Humanities (HUM) E5	Softball Field F2-F3
Child Care Center D2	Knuth Hall F6	Student Services (SSB) D5
Comm. Involvement Center (CIC) C7	Lakeview Center (LVC) A1-B2	Studio Theatre D5
Compass D9	Little Theatre D8-B8	Sutro Library D4
Coppola Theatre D6	Mail Services E7 Above Lot 25 (Winston Dr.) A1
Corporation Yard A3	Mary Park Hall A3-B4	Temporary Buildings A7-A8, B8, D8
Creative Arts (CA) E6-E7	Mary Ward Hall E2-E3	Thornton Hall (TH) A7-B7
Dining Center D3	Mekenna Theatre F6	The Towers D3-D4
Ethnic Studies & Psychology (EP) C6	One Stop Center D5	University Club E7
Facilities B3	Parking Garage B4-C4	University Park F2-F10
Fine Arts (FA) D6-E6	Parking & Transportation B3	Village at Centennial Square D4

Access symbol key

	Accessible Men's Restroom
	Accessible Women's Restroom
	Accessible Unisex Restroom
	Accessible Entrance with Power Door
	Accessible Emergency Telephone
	Accessible Parking (#'s indicate floors)

Access path key*

..... Accessible Route—This path generally conforms to accessibility standards.

..... Ramp (5%–8.3%)—Complying ramp along the accessible route.

..... Partially Accessible Route—This path generally conforms to accessibility standards, but there may be excessive cross-slope (over 2% or other irregularities in a portion of the path, often along the path edge. There is usually a 48" wide complying path along these routes, though it may not be a straight or direct line.

..... Areas that may be a travel hazard (where the slope exceeds the standard maximum ramp slope (8.33%), or the cross-slope is significant (exceeds 4%))

..... Lighter shade indicates path continues underneath overhang.

Symbol key

	Public Transit
	Shuttle Stops
	ATM Machines
	Parking Lots
	Metered Parking

Note: The map and information on pathways are limited by the scale. The accessible route should be clear to a person at a location, while the dashed line is intended to indicate where keener observation may be necessary to locate the accessible route. Pathways are generally asphalt and subject to weathering, erosion, uplifting, and other changes that may create navigational issues. SFSU is committed to maintaining the accessible route. Please report any irregularities to Disability Programs and Resource Center, 415/238-2472 (voice, TTY).

